UNITED STATES DEPARTMENT OF TRANSPORTATION

Legal: TRINITY INDUSTRIES DE MEXICO S DE R L DE CV Operating (DBA):

MC/MX #: 468284 RFC #: TIM9112096J4

Federal Tax ID: **Application Tracking #: 7434** 

**Review Type:** Safety Audit - Pre-Authority (OP1)

Scope: Location of Review/Audit: Company facility in another country **Entire Operation** Territory:

Operation Types Interstate Intrastate

Carrier: Non-HM N/A **Business:** Corporation

N/A **Gross Revenue:** \$1,715,812.00 for year ending: 12/31/2006 Shipper: N/A

Cargo Tank: N/A

**Company Physical Address:** 

CALZADA DE LAS MARISOLES LOTE 1 HUEHUETOCA, MX 54680

**Contact Name:** Francisco Laget Mera

Phone numbers: (1) (593) 918-026 Fax (2)

E-Mail Address:

**Company Mailing Address:** 

3490 HIGHWAY 277 NORTH EAGLE PASS, TX 78852

Process Agent Address:

3490 HIGHWAY 277 NORTH EAGLE PASS, TX 78852

**Contact Name:** Ruben Lara

**Phone numbers: (1)** (830) 773 091 (2) **Fax** 

E-Mail Address:

**Carrier Classification** 

**Private Property** 

Cargo Classification

Metal: Sheets, Coils, Rolls Machinery, Large Objects Other: Empty storage tanks

Does carrier transport placardable quantities of HM? No Is an HM Permit required? N/A

**Driver Information** 

Inter Intra Average trip leased drivers/month: 0 < 100 Miles: 0 0 **Total Drivers: 14** CDL Drivers: 14

>= 100 Miles: 14 0

Equipment

9/24/2007 3:32:19 PM

Owned Term Leased Trip Leased Owned Term Leased Trip Leased **Truck Tractor** 16 0 Trailer

Power units used in the U.S.:16

Percentage of time used in the U.S.:100

Page 1 of 2

Capri 6.5.1.3



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

## Part A

Questions about this report or the Federal Motor Carrier Safety or Hazardous Materials regulations may be addressed to the Federal Motor Carrier Safety Administration at:

Walker Plaza, 5810 San Bernardo Ave., Suite 290

Laredo, TX 78041

Phone: (956)712-1385 Fax:(956)723-1479

This SAFETY AUDIT will be used to assess your safety compliance.

Person(s) Interviewed

Name: Francisco Laget Mera Title: General Manager

Name: Ruben Lara Title: Export Manager

Page 2 of 2



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part B - Questions and Answers

Question General # 1 - Section # 387.7(a) Acute

Does the carrier have the required minimum level of financial responsibility in effect?

Comments

Question General # 2 - Section # 387.7(d) Critical

Does the carrier have required proof of financial responsibility?

**Comments** 

Question General #3 - Section #390.15(b)(1)

Can the carrier provide a complete accident register of recordable accidents?

**Comments** 

Question General #4 - Section #390.15(b)(2) Critical

Does the carrier have copies of all accident reports required by States or other government entities or

insurers? Comments

Question General #5 - Section #390.3(e)

Is the carrier knowledgeable of the FMCSRs/HMRs?

**Comments** 

Question General #6 - Section #390.21

Does the carrier know the commercial motor vehicles marking requirements?

**Comments** 

Question Driver # 1 - Section # 391.51(a) Critical

Does the carrier maintain complete driver qualification files?

**Comments** 

Question Driver # 2 - Section # 391.11(b)(4) Acute

Is the carrier using physically qualified drivers?

Comments

Question Driver # 3 - Section # 391.45(a), 391.45(b) Critical

Does available evidence indicate the motor carrier has used a driver without a medical certificate or with an

expired medical certificate?

Comments

Question Driver # 4 - Section # 391.15(a) Acute

Is the carrier using any disqualified drivers?

Comments

Yes

**Answer** 

**Answer** 

Yes

**Answer** 

N/A

Answer

N/A

Answer

Yes

**Answer** 

Yes

Answer

Yes

**Answer** 

Yes

Answer

No

Answer

No



Application Tracking #:7434

Review Date: 09/13/2007

RFC #: TIM9112096J4

### Part B - Questions and Answers

Question Driver # 5 - Section # 391.51(b)(2) Critical Answer Does the carrier maintain driving and employment history inquiry data in driver qualification files? Yes Comments Question Driver # 6 - Section # 382.115(a) Acute **Answer** Has the carrier implemented an alcohol and/or controlled substances testing program? Yes **Comments** Question Driver #7 - Section #382.213(b) Acute **Answer** Has the carrier used drivers who have used controlled substances? No Comments Question Driver #8 - Section #382.215 Acute Answer Has the carrier used a driver who has tested positive for a controlled substance? No **Comments** Question Driver # 9 - Section # 382,201 Acute Answer Has the carrier used a driver known to have an alcohol concentration of 0.04 or greater? No Comments Question Driver # 10 - Section # 382.505(a) Acute Answer Has the carrier used a driver found to have an alcohol concentration of .02 or greater but less than .04 within No 24 hours of being tested? Comments Question Driver # 11 - Section # 382.301(a) Critical <u>Answer</u> Has the carrier ensured that drivers have undergone testing for controlled substances prior to performing a Yes safety sensitive function? Comments

QuestionDriver # 12 - Section # 382.303(a) CriticalAnswerHas the carrier conducted post accident testing on drivers for alcohol and/or controlled substances?N/A

Comments

QuestionDriver # 13 - Section # 382.305 AcuteAnswerHas the carrier implemented random testing program?Yes

**Comments** 

Question Driver # 14 - Section # 382.305(b)(1) Critical
Has the carrier conducted random alcohol testing at an annual rate of not less than the applicable annual rate

Answer
Yes

of the average number of driver positions?

**Comments** 



Application Tracking #:7434

Review Date: 09/13/2007

RFC #: TIM9112096J4

### Part B - Questions and Answers

Question Driver # 15 - Section # 382.305(b)(2) Critical

Has the carrier conducted controlled substance testing at an annual rate of not less than the applicable annual

rate of the average number of driver positions?

Comments

Question Driver # 16 - Section # 40.305(a)

Has the carrier conducted the required return-to-duty tests on employees returning to safety-sensitive

functions?

Comments

Question Driver # 17 - Section # 40.309(a)

Is the carrier conducting follow-up testing as directed by the Substance Abuse Professional?

**Comments** 

Question Driver # 18 - Section # 382.211 Acute

Has the carrier used a driver who has refused to submit to an alcohol or controlled substances test required

under Part 382?

**Comments** 

Question Driver # 19 - Section # 382.503 Critical

Has the carrier used a Substance Abuse Professional as required by 49 CFR Part 40 Subpart O?

Comments

Question Driver # 20 - Section # 383.23(a) Critical

Has a driver operated a commercial motor vehicle without a current operating license, or a license, which

hasn't been properly classed and endorsed?

Comments

Question Driver # 21 - Section # 383.37(a) Acute

Has the motor carrier allowed it's drivers who's CDLs have been suspended, revoked or canceled by a state, have lost the right to operate a CMV in a State, or have been disqualified from operating a CMV to operate a

commercial motor vehicle?

Comments

Question Driver # 22 - Section # 383.51(a) Acute

Has the motor carrier knowingly allowed, required, permitted, or authorized a driver to drive who is disqualified

to drive a commercial motor vehicle?

Comments

Question Operation #1 - Section # 395.8(a) Critical

Does the carrier require drivers to make a record of duty status?

**Comments** 

Yes

Answer

Answer

N/A

Answer

N/A

Answer

No

Answer

N/A

**Answer** 

No

Answer

No

Answer

No

Answer N/A



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part B - Questions and Answers

Question Operation #2 - Section # 395.8(i) Critical

Does the carrier require drivers to submit records of duty status within 13 days?

**Answer** N/A

Comments

Question Operation #3 - Section # 395.8(k)(1) Critical

Can the carrier produce records of duty status and supporting documents for selected drivers?

**Answer** N/A

**Comments** 

Question Operation #4 - Section # 395.3(a)(1) Critical

Has the carrier allowed driver(s) to exceed the 11-hour rule? (Property)

**Answer** No

Comments

Question Operation #5 - Section # 395.3(a)(2) Critical

Has the carrier allowed driver(s) to exceed the 14-hour rule? (Property)

Answer

No

**Comments** 

Question Operation #6 - Section # 395.3(b)(1) Critical

Has the carrier allowed driver(s) to drive after having been on duty more than 60 hours in 7 consecutive days?

(Property)

Answer

No

**Comments** 

Question Operation #7 - Section # 395.3(b)(2) Critical

Has the carrier allowed driver(s) to drive after having been on duty more than 70 hours in 8 consecutive days?

(Property)

Answer

N/A

**Comments** 

Question Operation #8 - Section # 395.5(a)(1) Critical

Has the carrier allowed driver(s) to exceed the 10 hour rule? (Passenger)

**Answer** 

N/A

Comments

Question Operation #9 - Section # 395.5(a)(2) Critical

Has the carrier allowed driver(s) to exceed the 15 hour rule? (Passenger)

**Answer** 

N/A

Comments

Question Operation #10 - Section # 395.5(b)(1) Critical

Has the carrier allowed driver(s) to drive after having been on duty more than 60 hours in 7 consecutive days?

(Passenger)

Answer

N/A

**Comments** 

Question Operation #11 - Section #395.5(b)(2) Critical

Has the carrier allowed driver(s) to drive after having been on duty more than 70 hours in 8 consecutive days?

(Passenger)

Answer N/A

**Comments** 



Application Tracking #:7434

Review Date: 09/13/2007

RFC #: TIM9112096J4

### Part B - Questions and Answers

Question Operation #12 - Section # 395.8(e) Critical

Does available evidence indicate a selected driver has prepared a false record of duty status?

Comments

Question Operation #13 - Section #

Does the carrier adhere to a disciplinary policy for noncompliance with Part 395?

Comments

Question Operation #14 - Section # 395.1(e)

Does the carrier have a system for recording hours of duty status on 100- mile radius drivers, and are they properly utilizing the 100 air-mile radius exemption?

**Comments** 

Question Operation #15 - Section # 392.2 Critical

Does the motor carrier ensure that drivers operate commercial motor vehicles in accordance with the laws, ordinances, and regulations of the jurisdictions in which they are operating?

**Comments** 

Question Operation #16 - Section #392.9(a)(1) Critical

Does the carrier ensure that drivers are not permitted to drive a vehicle without the cargo properly distributed and adequately secured?

Comments

Question Operation #17 - Section # 392.4(b) Acute

Have any drivers operated a commercial motor vehicle while under the influence of, or in possession of, narcotic drugs, amphetamines, or any other substances capable of rendering the drivers incapable of safely operating motor vehicles?

**Comments** 

Question Operation #18 - Section # 392.5(b)(1) Acute

Have any drivers operated a commercial motor vehicle while under the influence of, or in possession of, intoxicating beverages?

Comments

Question Operation #19 - Section # 392.5(b)(2) Acute

Have any drivers operated a commercial motor vehicle within 4 hours of having consumed intoxicating beverages?

Comments

Question Maintenance # 1 - Section # 396.3(b) Critical

Can the carrier produce maintenance files for requested vehicle(s)?

**Comments** 

Answer No

**Answer** 

Yes

**Answer** 

Yes

Answer

Yes

Answer

Yes

**Answer** 

No

Answer

No

Answer

No

Answer

Yes



Application Tracking #:7434

Review Date: 09/13/2007

RFC #: TIM9112096J4

### Part B - Questions and Answers

Question Maintenance #2 - Section #396.17(a) Critical

Can the motor carrier produce evidence of periodic (annual) inspections for selected vehicles?

Comments

Question Maintenance #3 - Section #396.11(a) Critical

Does the motor carrier require drivers to complete vehicle inspection reports daily?

**Comments** 

Carrier does not require drivers to complete daily vehicle inspection

**Driver Name:** 

Trip Date: 08/29/07

VIN #: 1FUYDCXB7YPA51090

Question Maintenance # 4 - Section # 396.11(c) Acute

Does the carrier ensure that out-of-service defects listed by the driver in the driver vehicle inspection reports

are corrected before the vehicle is operated again?

**Comments** 

Question Maintenance # 5 - Section # 396.9(c)(2) Acute

Does the carrier ensure vehicles that have been declared "out-of-service" do not operate before repairs have

been made?

Comments

Question Maintenance # 6 - Section # 396.19

Is the carrier using qualified inspectors (mechanic) and maintaining evidence of the inspector's qualifications?

Comments

Question Maintenance #7 - Section #396.3

Can the carrier explain its systematic, periodic maintenance program?

**Comments** 

Question Other #1 - Section #375.211

Does the carrier participate in an Arbitration Program?

**Comments** 

Question Other # 2 - Section # 13702

Does the carrier assess shipper freight charges based upon published tariffs?

Comments

**Question** Other # 3 - Section # 375.401(c)

Does the carrier provide reasonably accurate estimates of moving charges?

**Comments** 

**Question** Other # 4 - Section # 375.407(a), 375.703(b)

Has the carrier avoided "hostage freight" or other predatory practices?

Comments

Answer Yes

**Answer** 

No

Answer

N/A

Answer

Yes

Answer

Yes

Answer

Yes

**Answer** 

N/A

**Answer** 

N/A

**Answer** 

N/A

Answer

N/A





Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part B - Questions and Answers

**Question** Other # 5 - Section # 387.301(a), 387.301(b)

Does the HHG carrier have sufficient levels of public liability and cargo insurance?

Comments

<u>Answer</u>

N/A

Question Other #6 - Section #13901

Is the motor carrier authorized to conduct interstate operations in the United States?

Answer Yes

**Comments** 

Note: No Hazardous Materials questions were asked because the carrier does not carry Hazardous Materials in Interstate Commerce.



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

# Part B Requirements and/or Recommendations

1. Una copia de el portafolio de su documento del Auto transportista puede ser obtenida por \$ 20.00 dólares en la siguiente página de seguridad de el Internet (www.safersys.org) o por teléfono llamando al 1-800-832-5660 o 703-280-4001. Ud. también puede escribir a: Computing Technologies, Inc P O Box 3248

Merrifield, VA 22116-3248.

El costo del documento si es ordenado por teléfono o correo es de \$27.50 dólares.

- 2. Mantener en archivo una copia completa y actualizada de su forma de responsabilidad de endoso financiero MCS-90 (Administración Federal de Seguridad-90).
- 3. La Administración Federal de Seguridad de Auto transportista tiene una versión en Español en la siguiente página del Internet: www.fmcsa.dot.gov/spanish



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part C

Corporate Contact: Francisco Laget Mera
Corporate Contact Title: General Manager

**Special Study Information:** 

#### Remarks:

- (a) The motor carrier has been in operation since September 1990.
- (b) The motor carrier is currently operating within the Unites States municipalities and commercial zone.
- (c) The motor carrier received a certificate of registration to operate within the United States municipalities and commercial zone on 09/09/2003.
- (d) The motor carrier is currently operating within the United States commercial zone, the motor carrier has not had any expedited action letters. The carrier had a safety audit review on 12/31/2003 with a commercial zone PASS letter dated 12/06/2005.
- (e) If long-haul operating authority is granted, the carrier has plans to operate within the United States municipalities and commercial zones as well.
- (f) The motor carrier does have a parent company with a motor carrier operating in the United States.
- (g) The motor carrier operates 16 CMVs in Mexico plus a total of 50 in Mexico only.
- (h) The Advisement of Obligation to Comply with Statutes and Regulations was discussed with the motor carrier official and a copy of the signed and dated form was provided to the carrier.
- (i) The motor carrier officials present during the discussion of the Advisement were Mr. Francisco Laget Mera, Mr. Ruben Lara and Miss. Ivonne De La Rosa. The Protested Application Process was discussed and a copy was provided to the motor carrier.

Our initial contact to schedule the PASA with Mr. Francisco Laget Mera V.P. was on 08/23/07. The PASA began at 09:30 a.m. on 09/11/07. Upon our arrival we were greeted by Mr. Francisco Laget Mera V.P.

Safety Investigator Luis Lopez and I were accompanied by a SCT representative whose name was Angel Garcia Villanueva. After introducing all personnel and explaining the purpose of our visit, the carrier provided a tour of the facility. The carrier directed us to a location for the PASA to be conducted.

I asked the carrier if they had previously been contacted by the SCT, regarding the PASA and he answered yes. Mr. Francisco Laget Mera stated that they received a call on 08/23/07 from the SCT office.

Mr. Francisco Laget Mera was advised of all the requirements that must be met before OP-1 authority is granted as a long-haul carrier.

The carrier was provided a copy of the OCE-46, which was properly signed, dated and executed by the carrier. The Reinstatement of OP-2 Operating Authority was also signed and dated by the carrier.

A thorough explanation was provided to Mr. Francisco Laget Mera, in order to ensure full understanding of the Advisement of Obligation to Comply with Statues and Regulations. The carrier agreed to all obligations explained and the form was signed and dated, after which a copy of the advisement was provided to the carrier.

We next proceeded to start the verification process (Phase 1 of the PASA) and questioned the carrier regarding each of the five mandatory elements. After we assured each of the five mandatory elements were satisfied, we provided with copies of various forms and information of required documents to be utilized by the carrier and kept on file to assist in compliance with the FMCSR.

The carrier owns 16 truck tractors and 9 semi trailers, which were originally planned on using if granted OP-1 Authority. It should be noted that upon our level 5 inspections 25 of the CMVs do meet the Federal Motor Vehicle Safety Standards (FMVSS) as required. Mr. Francisco Laget Mera stated they would only use the 25 vehicles meeting the safety standards.



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part C

Changes were not made or needed to the OP-1 application, as information on file is current, up to date and correct.

The CAPRI process (Phase II of the PASA) Pilot Program was conducted on 09/13/07 at carrier's Place of Business located at Calzada de los Marisoles Lote 1, Huehuetoca Edo. De Mexico. Present for the PASA were Mr. Ruben Lara, Miss. Ivonne De La Rosa, and Mr. Francisco Laget Mera, who signed and received a copy of Part A (Page 1 and 2) and Receipt Page of the report.

Review of Part 387: The carrier is currently operating with OP-2 authority and provided proof of insurance along with copy of MCS-90. The current effective Policy ISAH0823068-7 for Mc Queary Henry Bowles Troy LLP was verified, and confirmed by contacting Linda Stewarts Account manager for Trinity account located at 12700 Park Central Drive 7th floor Dallas TX 75251, contact number (972) 770-1600.

Review of Part 383: CDLIS check inquiry of the 19 driver's on the list created by the carrier to operate in the US revealed a valid Licencia Federal for only 14 drivers of the 19 the rest came back with a restriction to drive only in Mexico. Another list was made by auditor Mario Escamilla with the names of the 14 drivers eligible to drive in the US and will be scanned with the original list created by the carrier. Copies of CDLIS inquiry are included in this review, as well as a copy of the Licencia Federal de Conductor provided by the carrier for each driver planning to travel beyond the commercial zone.

Review of Part 40 and 382: The motor carrier has a Drug and Alcohol Testing Program. The carrier has a Random Testing Program run by a consortium. Discrepancies were not found as the carrier is correctly following the procedures for random testing selections. The collection site conducting the controlled substance and alcohol testing was contacted by phone. We spoke to CAD Services located at 1315 Del Rio Blvd. Eagle Pass, TX 78852, contact number (956) 773-4333. Raquel Palacios representative stated they utilize Nedtox Laboratories, located at 402 West Country Road D, Saint Paul, Minnesota, 55112 as their certified laboratory. Confirmation from the collection site was provided that they do conduct pre-employment, random, post accident, and reasonable suspicion controlled substance/alcohol testing, but the collection site has no involvement in the random selection process. The carrier was also advised of the required Supervisor Training under 382.603. The D&A regulations were discussed in-depth with the carrier.

Review of Part 390: The motor carrier has had zero recordable accidents in the last 12 months. The carrier was made aware of the definition of an accident involving a CMV and the requirements of documents to be maintained on file. The carrier has had zero recordable accidents in the territory of Mexico. The motor carrier was notified of the marking requirements in the event they are granted provisional operating authority.

Review of Part 391: The list of drivers created by the carrier details the drivers they are planning to operate in the United States however the list will have to be modified do to the fact some of the drivers have Licencias Federales with a restriction to drive only in Mexico. DQ files for each driver were reviewed and no discrepancies were discovered.

Review of Part 395: The motor carrier produced time cards and supporting documents for all drivers. A review of 30 day time card for each driver was completed. The carrier was advised and explained on the importance and responsibility of keeping accurate and legitimate RODS. The carrier was also instructed on the required retention period for such records. The carrier stated he has a verbal disciplinary policy for non-compliance with Part 395. A total of eight days of Time Cards were scanned. Carrier also was told if in the future they receive the OP-1 authority, the drivers will have to start utilizing log books instead of the time cards since they will be traveling from Monclova CH to the Dallas TX area, the carrier does have logs ready to be use and a copy of one of this logs was scanned into EDMS.

Review of Part 396: The motor carrier was able to produce complete maintenance files for all selected vehicles they intend to operate in the United States. Current copies of annual inspections were on file. The carrier can not produced Driver Vehicle Inspection Reports for the selected vehicles at the time of the audit. The carrier was advised of the importance of having the Driver Vehicle Inspection Report and the required retention period for such records. The motor carrier explained its systematic periodic maintenance program. The carrier is aware that a scheduled maintenance program must be kept on a daily basis when vehicles are used. Level V inspections were performed at the carriers' facility as required by the PASA Memorandum guidance on the vehicles available which will be operating in the United States. A safe and convenient area where the Level 5 inspections are to be conducted was designated.

Inspection Report Number US0980000876 revealed zero critical item violation for unit number 094. Truck Tractor, Kenworth 2006, Mexican License Tag 205FB4, VIN-3WKDD40X36F631296, Gross Vehicle Weight Rating 59,124 LBS was issued CVSA Decal 6654583.



Application Tracking #:7434

RFC #: TIM9112096J4

**Review Date:** 09/13/2007

### Part C

Inspection Report Number US0980000877 revealed zero critical violations for unit number 097. Truck Tractor Kenworth 2006, Mexican License Tag 786FB4, VIN-3WKDD40X57F801661, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654582.

Inspection Report Number US0980000878 revealed zero critical violations for unit number 098. Truck Tractor Kenworth 2006, Mexican License Tag 208FB5, VIN-3WKDD40X17F804024, Gross Vehicle Weight Rating 59,124 Lbs was Issued CVSA Decal 6654584.

Inspection Report Number US0980000879 revealed zero critical violations for unit number 084. Truck Tractor Kenworth 2006, Mexican License Tag 195FB4, VIN-3WKDD40X06F631286, Gross Vehicles Weight Rating 59,124 Lbs was issued CVSA Decal 6654585.

Inspection Report Number US0980000880 revealed zero critical violations for unit number 99. Truck Tractor Kenworth 2006, Mexican License Tag 209FB5, VIN-3WKDD40X37F804025, Gross Vehicles Weight Rating 59,124 Lbs was issued CVSA Decal 6654586.

Inspection Report Number US0980000881 revealed zero critical violations for unit number 083. Truck Tractor Kenworth 2006, Mexican License Tag 175FB4, VIN-3WKDD40X36F629080, Gross Vehicles Weight Rating 59,124 Lbs was issued CVSA Decal 6654587.

Inspection Report Number US0980000882 revealed zero critical violations for unit number 085. Truck Tractor Kenworth 2006, Mexican License Tag 196FB4, VIN-3WKDD40X26F631287, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654588.

Inspection Report Number US0980000883 revealed zero critical violations for unit number 103. Truck Tractor Kenworth 2007, Mexican License Tag 585FB5. VIN-3WKAD40X17F806522, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654589, and for the semi trailer unit number T-074, VIN-982PCDS6388 with Mexican License Tag 2HU6141 also revealed zero critical violations and a CVSA decal # 6654590 was issued.

Inspection Report Number US0980000884 revealed zero critical violations for unit number 101. Truck Tractor Kenworth 2007, Mexican License Tag 583FB5, VIN-3WKAD40X57F806278, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654593, and for the semi trailer unit number T-041, VIN-962PCDS626Z with Mexican License Tag 2HU6179 also revealed zero critical violations and a CVSA Decal # 6654592 was issued.

Inspection Report Number US0980000885 revealed zero critical violations for unit number 090. Truck Tractor Kenworth 2006, Mexican License Tag 201FB4, VIN-3WKD040X66F631292, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654594, and for the semi trailer unit number T-047, VIN-972PCDS6274 with Mexican License Tag 2HU6145 also revealed zero critical violations and a CVSA Decal # 6654595 was issued.

Inspection Report Number US0980000886 revealed zero critical violations for unit number 093. Truck Tractor Kenworth 2006, Mexican License Tag 204FB4, VIN-3WKD040X1BF631295, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654596, and for the semi trailer unit number T-029, VIN-912PCDS5818 with Mexican License Tag 2HU7149 also revealed zero critical violations and a CVSA Decal # 6654597 was issued.

Inspection Report Number US980000887 revealed zero critical violations for unit number 092. Truck Tractor Kenworth 2006, Mexican License Tag 203FB4, VIN-3WKD040XX6F631294, Gross Vehicle Weight Rating 59,124 Lbs was issued CVSA Decal 6654606, and for the semi trailer unit number T-030, VIN-912PCDS5821 with Mexican License Tag 3HU3389 also revealed zero critical violations and a CVSA Decal #6654607 was issued.

Inspection Report Number US0778001163 revealed zero critical violations for unit number 105. Truck Tractor Kenworth 2007, Mexican License Tag 587FB5, VIN-3WKAD40X57F806524, Gross Vehicle Weight Rating 59,130 Lbs was issued CVSA Decal 6654604, and for the semi trailer unit number T-048, VIN-972PCDS6275 with Mexican License Tag 2AV7149 also revealed zero critical violations and a CVSA Decal #6654605 was issued.

Inspection Report Number US0778001164 revealed zero critical violations for unit number 091. Truck Tractor Kenworth 2006, Mexican License Tag 202FB4, VIN-3WKDD40X86F631293, Gross Vehicle Weight Rating 59,130 Lbs was issued CVSA Decal 6654602, and for the semi trailer unit number T-083, VIN-982PCDS with Mexican License Tag 3HU416 also revealed zero critical violations and a CVSA Decal #6654603 was issued.



Application Tracking #:7434

RFC #: TIM9112096J4

Review Date: 09/13/2007

### Part C

Inspection Report Number US0778001165 revealed zero critical violations for unit number 089. Truck Tractor Kenworth 2006, Mexican License Tag 200FB4, VIN-3WKD0X46F631291, Gross Vehicle Weight Rating 59,130 Lbs was issued CVSA Decal 6654600, and for the semi trailer unit number T-056, VIN-972FCE61288 with Mexican License Tag 2HU6203 also revealed zero critical violations and a CVSA Decal #6654601 was issued.

Inspection Report Number US0778001166 revealed zero critical violations for unit number 081. Truck Tractor Kenworth 2006, Mexican License Tag 173FB4, VIN-3WKDD40X56F629078, Gross Vehicle Weight Rating 59,130 Lbs was issued CVSA Decal 6654598, and for the semi trailer unit number T-039, VIN-CJG3F4045 with Mexican License Tag 2AV6157 also revealed zero critical violations and a CVSA Decal #6654599 was issued.

Maintenance files were verified of repairs made for vehicles that were placed Out Of Service during road side inspections capture on carrier profile.

The motor carrier had 572 inspections listed on company profile. Web sites reviewed for carrier information include MCMIS, QUERY CENTRAL, SAFER, L&I, CDLIS, EMIS, PC MILER, PRO VU AND PIQ. Throughout the PASA the carrier was courteous, attentive and receptive of recommendations made. The carrier displayed a sincere desire to comply with all applicable regulations.

The motor carrier is aware they must be in full compliance to avoid any future violations.

Upon completion of the PASA, I reviewed with Mr. Francisco Laget Mera, the Protest Procedures flowchart "Attachment 5" from the PASA memo. I notified the motor carrier of the possibility of a protest to their application for OP-1 long haul operating authority, and if a protest is filed the time limits to respond to a protest. I provided a copy of the Protest Procedures flowchart to Mr. Francisco Laget Mera.

Upload Authorized: Yes No
Authorized by: Date:
Uploaded: Yes No Failure Code:
Verified by: Date: